

CS PM 600 - Mobile current/effective power meter suitable for: DS 500 mobile / DS 400 mobile / PI 500

Measures voltage, current and calculates:

Effective power [kW] [kVA] Apparent power Reactive power [kVar] Active energy [kWh] cos phi



Magnetic voltage measuring tips electrically isolated



Special features:

- Magnetic voltage measuring tips for picking off the voltage during operation
- Hinged current transformers encompass the conductors of the phases L1, L2, L3. This can also be done during operation

All measured data are transferred digitally (Modbus) to DS 500 mobile/ DS 400 mobile and can be recorded there.



Example: Measurement on the compressor

TECHNICAL DATA CS PM 600

Parameters:

Voltage (Volt) Current (Ampere) Cos phi

Effective power (kW) Apparent power (kVA) Reactive power (kVar) Active energy (kWh) Power frequency (Hz) All parameters are transferred digitally to DS 500 mobile /DS 400 mobile

Accuracy current measurement:

Threshold values for current deviation. Loss angle according to IEC 60044-1. Current deviation in % at

rated current in 120% 100% 20% 1.5 5% 3

Accuracy active energy:

IEC 62053-21 Class 1

Sensor connec-3 x current transformers tions: (L1,L2,L3,N)

4 x voltage measurement

(L1,L2,L3)

Interfaces: RS 485 (Modbus protocol)

Measuring Voltage measurement max. 400 Volt (in special version

> up to 480V) Current measurement max.

100 A or 600 A

Size current transformers:

range:

100 A / 1 A (max. 24 mm wire),

600 A / 1 A (max. 36 mm wire) 270 x 225 x 156 mm

Dimensions

 $(B \times H \times T)$

DESCRIPTION ORDER NO. CS PM 600 mobile current/effective power meter 100 A 0554 5341 CS PM 600 mobile current/effective power meter 600 A 0554 5342 Mobile current/effective power meter with 3 external current transformers for big machines and systems External current transformers for encompassing the phases (100 A or 600 A) External magnetic measuring tip for measuring the voltage Measures kW, kWh, cos, phi, kVar, kVA Data transfer via Modbus

instruments. 5 m Current transformer 100A/1A consisting of 3 transformers for mobile instruments Current transformer 600A/1A consisting of 3 transformers for mobile instruments Current transformer 1000A/1A consisting of 3 transformers for mobile instruments

Incl. connection cable for mobile current/effective power meter to mobile

Z554 0001 Z554 0002 Z554 0003

Operating temperature:

- 10...+40 °C